

Alloys: →

When two metals are heated together or a metal is mixed with a non metallic element, then one of the following will occur. —

(1) An ionic compound may be formed.

(ii) An interstitial alloy may be formed.

(iii) An substitutional alloy may be formed.

(iv) A simple mixture may result.

Interstitial alloys: →

The structure of many metals in a closed packed lattice of spherical atoms or ions. Therefore many tetrahedral and octahedral holes ^{may result}. If the element added has small atoms, they can be accommodated in these holes without alternating structure.

of metal, the ^{invading} atoms occupy interstitial positions in the metal lattice instead of replacing the metal atoms. Such alloys are called interstitial alloys. The chemical composition of compounds of this type may vary over wide range depending on how many holes are occupied. These are formed by wide range of metals with hydrogen, boron, nitrogen and other elements.

The most important factor is the size of invading atom. For octahedral holes to be occupied the radius ratio of smaller atom by the larger atom should be in the range of $0.414 - 0.732$ and for tetrahedral holes it should be $0.225 - 0.414$.

The invasion of interstitial sites does not significantly alter the metal structure and it still ~~con~~ conducts heat & electricity. However, filling some of the holes has a considerable effect on the physical properties particularly the hardness, malleability and ductility of the metal. This is because filling of the voids make it much more difficult for one layer of metal ion to slide over another. For eg. interstitial borides, carbides, and nitrides are extremely inert chemically, have very high

melting points and are extremely hard. steel contains upto 2% carbon which makes it harder and brittle. when steel is heated, the solids form austenite, which can be hot rolled out or pressed into any required shape. the properties of steel can be changed by annealing and tempering. cast iron contains more than 2% carbon. Iron carbide is extremely hard and brittle.

Substitutional Alloy: →

If two metals are completely miscible with each other then one atom may replace another at random in the lattice and they can form a continuous solid solⁿ. such are called substitution alloys. eg. Cu/Ni, Cu/Au, K/Rb, K/Cs, Rb/Cs.

Hume-Rothery has shown that for metals to form continuous solid solution or for complete miscibility, the following rules must be followed.

- ① Both metals must be similar in size and their metallic radii must not differ by more than 14-15%.
- ② Both metals must have same ~~metal~~ crystal structure.
- ③ The chemical properties of a metal must be similar, in particular the no. of valance-electrons should be the same. For eg. → let us consider an alloy of Cu and Au. the metallic radii differ

Only by 1:5:1 both has CCP lattice and both have similar properties. The two metals are therefore completely miscible. Similarly K and Rb size difference is 9.3%, Rb and Cs size difference is 8.9%, and hence they are completely miscible. but Li and Na size differ is 22.4%. Na and K are 22%, and hence they are not miscible.

If only one or two of these rules are satisfied then random substitutional solid will occur. For eg. consider an alloy of Sn and Pb (solder). The radii differ by 8% and have similar properties but they differ in their structures. and hence they will form random substitutional alloys. The similar behaviour is found in with Na-K alloys, and Al-Cu alloys.

In other cases where only a limited range of solid solutions are formed. The larger tendency of the different metal to form compounds instead of solution is important. In such cases intermetallic phases exist, each of which behaves as a compound of the constituent metal. For eg: → In the Cu/Cu-Zn system, the metallic radii differ by 7%, but they have different structures (Cu CCP and Zn HCP) and they also have different no of valance electrons. So only a limited range of solid solutions is expected.

but the atoms have a strong tendency to form compounds and the different structures may be distinguished as follows

α (Xn-0-35%)

ρ (45-95% Zn)

δ (50-65% Zn)

ξ (82-88% Zn)

η (97-100% Zn)

According to Hume-Rothery ρ -phase occurs in the alloys where the ratio of valance e-'s to the no of atoms is 3:2, δ -phase occurs when the ratio is 21:13. And η phase occurs when the ratio is 4:4.

eg: 3:2 \rightarrow ρ -phase

Cu, Zn, Cu_3Al , $CoZn_3$,

Ag_3Al

21:13 \rightarrow δ phase

Cu_5Zn , Cu_9Al_4 , $Na_{31}Pb_6$

4:4 \rightarrow η phase

$Cu_{13}Zn_3$, Cu_3Si , Ag_5Al_3 ,

Au_5Al_3